

LTR-1000-200783

2018/06/14

No



**To: Mr.E.A Salkov**

**Director General of Rusatomservice**

**Sub: Emergency Supply of Spare Parts**

Dear Sir,

Please be informed that due to the defect found on Hydrogen gas analyzer with AKZ: 10ST41A001, and also lack of spare part at BNPP-1 site, one set of the aforementioned analyzer should be supplied as reserve. Therefore, you are kindly requested to give instructions to the relevant department to immediately supply the item with serial No.2-C10.14-007.0418 of payment from the Appendix 1.1 to the Contract SP-BNPP-1/2018/309/1575 as mentioned in the table below.

Serial No. of payment (UID)	AKZ code of equipment	Safety class	Name of equipment/ Spare part	Type, mark, spare part drawing
2-C10.14-007.0418	10ST41A001	4H	Hydrogen gas analyzer	ГТВ-1101М ИБЯЛ.413211.007-19 90-100%

Your best efforts are highly appreciated.\

**Sincerely yours**

**H.Ghaffari**

**Bushehr NPP Manager and Managing Director**