



РУСАТОМ СЕРВИС

RUSATOM SERVICE JSC

+7 (495) 995 7680

info@rusatomservice.ru

17 AUG 2018

№

309/04/5442

your ref. №

date

H. Ghaffari
Manager and Managing Director
Bushehr Nuclear Power Plant

bnpp@nppd.co.ir

R. Bannazadeh
Director General
TAPNA

bannazadeh@nppd.co.ir

Subject: Request for Documentation

Dear Mr. Ghaffari,

We are kindly asking you to send us the below listed documents to enable development of alternative suggestions for inspection of metal of weld joints of ПГБ-1000М (B)-series steam generators of Unit No. 1 of the Bushehr NPP:

38-CK016M.00.00.00.00.00 Д3 System for Inspection of Heat-Exchange Tubes, Crossover Legs, and Weld Joints of Steam Generator Headers. TV Inspection Procedure;

38-CK016M.00.00.00.00.00 Д4 System for Inspection of Heat-Exchange Tubes, Crossover Legs, and Weld Joints of Steam Generator Headers. Ultrasonic Inspection Procedure.

Aleksei Emelianov
Deputy Director General –
Technical Director



Vsevolod Cherkesov
+7(495)995-76-80 ext 128



POCATOM