

RUSATOM SERVICE JSC +7 (495) 995 7680 info@rusatomservice.ru

24.07.2018 No 2	<u>9/02-02/4801</u>
-----------------	---------------------

your ref. № date\_\_\_\_

H. Ghaffari Manager and Managing Director Bushehr Nuclear Power Plant

bnpp@nppd.co.ir

R. Bannazadeh Director General TAPNA

bannazadeh@nppd.co.ir

Submission of documents

Dear Mr. Ghaffari,

Pursuant to item 1 of the M.O.M. "On a damaged end contact seal body (drawing 1391-05-0101) of RCPS-1391 at Unit 1 BNPP", please find attached to this letter the set of technical documentation for repair of the a.m. body.

We are kindly asking you to consider and agree the set of repair documentation before 30.07.2018 as it stated by the item 2 of the M.O.M.

Attachment: set of technical documentation for repair of the end contact seal body – on 13 pages.

Deputy Technical Director

July

Vasiliy Zabavin



