

RUSATOM SERVICE JSC +7 (495) 995 7680 info@rusatomservice.ru

| 14.05.2018 | N₂ | 309/03 | 03/3091 |
|------------|----|--------|---------|
|------------|----|--------|---------|

your ref. № _____ date _____

Mr. H. Ghaffari The Bushehr Nuclear Power Plant Manager and Managing Director

Copy to NPPD

On procedure of the Incoming Control

Dear Mr. Ghaffari,

We refer to the Contract for delivery of spare & replacement parts and reserve equipment for Bushehr NPP SP-BNPP-1-2017/309/1265-D dated May 2017 (The Contract).

Please be informed that currently the Incoming Control reports have been signed only for a part of the delivered Goods. However, the Warehouse receipt of the fifth set of Goods was signed on March 23, 2018. Please note that Incoming Control reports should be signed by the Customer not later than one month after signing of the Warehouse receipt according to the i.11 of the Appendix No.7 to the Contract.

Delay in signing of the Incoming control reports causes the delay in signing of Provisional acceptance certificates, in approving of the documents by the Central Bank of Iran and, therefore, in the final customs clearance.

1-11/8

We kindly ask you to expedite the procedure of the Incoming control.

Project Director

Andrey Shikankov



