



RUSATOMSERVICE

RUSATOM SERVICE JSC
+7 (495) 995 7680
info@rusatomservice.ru

06 ИЮН 2018

№

30 9/03-01/36 93

your ref. №

date

Mr H. Ghaffari
Manager and Managing Director
The Bushehr Nuclear Power Plant

Copy to: NPPD

On NCR No. 1513-2-3-00527
dated March 04, 2018

Dear Mr Ghaffari,

We refer to the Contract for delivery of spare & replacement parts and reserve equipment for Bushehr NPP Unit-1 No. SP-BNPP-1-2017/309/1265-D dated May 2017 (The Contract).

We have received the IC-1 report No. 1513-2-2-00800 dated March 04, 2018 considering the Goods of JSC SNIIP (the Warehouse receipt No. 1513-2-1-417 dated February 17, 2018). We have also received the Noncompliance report No. 1513-2-3-00527 dated March 04, 2018 considering the safety classes of Resistance thermal converters TCI9201, TCI9203, TCI9204 TCI9417.

We regret to inform you that the NCR No. 1513-2-3-00527 dated March 04 cannot be approved by the Supplier. The aforementioned equipment with Safety class "4" was delivered to the Customer according to the Appendix No.1 to the Contract that was signed by the Customer.

The Supplier has contacted the sub-contractor JSC SNIIP and the manufacturer JSC NPP Etalon. The aforementioned equipment was manufactured in strict compliance with the license CO-12-101-2123 dated July 10, 2014 and only with safety class "4H".

Nevertheless, we fully understand the Customer's concern. Therefore, to come to the final solution, we kindly ask you to send us copies of technical documentation (passport, certificate) that could clearly specify that the aforementioned equipment had been delivered with safety classes "2Y" and "3H".

Project Manager

Vladimir Bozrikov



Denis Boldin

+7(495)995 76 80, ext. 286

