



RUSATOMSERVICE

RUSATOM SERVICE JSC  
+7 (495) 995 7680  
info@rusatomservice.ru

16 OKT 2018

№ 309/02/4040

your ref. № \_\_\_\_\_ date \_\_\_\_\_

Mr. M. Shirazi,  
BNPP Chief Engineer  
bnpp@nppd.co.ir

Mr. R. Bannazadeh,  
TAPNA Co Director  
bannazadeh@nppd.co.ir

**Subject: Spare Parts for Turbine Repair  
During MR-2019 of BNPP-1**

Dear Sirs,

I am kindly asking you to inform *JSC Rusatom Service* whether spare sets of fasteners for repair/replacement of the rotor blades of the 5<sup>th</sup> stages of the low-pressure rotors of steam turbine K-1000-60/3000-3 are available at the *Bushehr* NPP Site. This information is necessary for preparation for the 2019 Medium Repair and was requested by *PJSC Power Machines*. You can find the list of items in the said sets in the Table below.

Table

Name	Drawing number
Segment of non-soldered wire Ø16	1277733
Segment of non-soldered wire Ø16	1277734
Stop wedge	1291614
Segment of non-soldered wire Ø14	1330247
Segment of non-soldered wire Ø14	1300247-01
Locking plate	1354332
Locking plate	1354332-01
Welding titanic wire Ø2 BT1-00	311483
Insert	Э-77244
Insert	Э-77244-01
Insert	Э-77244-02
Insert	Э-77244-04

Alexey Emelianov,  
Deputy Director General – Technical Director



Vitaly Shevnin  
+7(495) 995-76-80 ext.127.

